## REVIEW

## Potential Hazardous Waste Site - Site Inspection Report

Site Name	Gould, Inc.	)		<u> </u>	<u>`</u>
Site Location	Frisco, Texa	<u>s</u>			
Site Number_	TX-11029		Date of Survey_	5/9/84	·
Inspected by_	,	StateFIT_	TAT		
		Other (specia	fy) <u>Engineering Sci</u>	ence, Inc	· ·
Date rec'd by	Water Supply	Branch 3/1	.2/85		<del></del>
Type samples:					
<u> </u>	n-site		Xon-site		on-site
X_SOIL	X	SURFACE WA	TER	GR OUNI	D WATER
<u> </u>	f-site		Xoff-site		off-site
	•			,	
	<del></del>	on-site			-
DRINKIN	G WATER				·
·		off-site	•		
Type contamin	ant(s):			•	
ORGANIC	S X INC	ORGANI CS	RADIONUCLIDES	·	MI CROBIOLOGI CAL
Summary:		_			<b></b> 
According to	the manant ti	ho anoundwate	on coome to flow in	+60 0000	-i+-
direction from	m the PWS. TI	he concentrat	er seems to flow in tions of lead and o	admium do	not
seem signific	ant enough to	affect the s	surface water at Le ter source and is a	wisville l	_ake °
away from the	site. The d	istance would	lallow time for c	ontaminant	ts to
settle out of this site.	the water. 1	We agree with	n the low hazard ra	ting assig	gned to
				S	SUPERFUND FILE
,		•			
	•				MAR 04 1992
		N.A.	Λ /	<u> </u>	REORGANIZED
		fron	More M.O	of a Ma	3-18.85

TXD 006451090